



Job Title: Roustabout
Department: Operations
Location: Appalachian Region

Summary:

Under the supervision of the Production Foreman and/or the Production Superintendent, the Roustabout will inspect, repair and maintain high pressure production equipment on new and existing wells. The Roustabout will fill in for Operators on an as needed basis. The Roustabout must be able to work independently and follow all safety rules.

Education/Qualifications:

1. High school diploma or equivalent.
2. Minimum 3 years related experience, preferred.

Requirements/Skills:

1. Must be familiar with high pressure production equipment and operations.
2. Experience with various regulators, motor valves, pipe and pipe fittings.
3. Must be able to read and understand directions.
4. Must possess good written and verbal communication skills.
5. Must possess basic computer skills including experience with Microsoft Office products.
6. Valid driver's license.

Job Duties and Responsibilities:

- Replace or repair fittings, valves and all pipeline related issues for daily operations in all current production fields.
- May oversee new construction projects, including coordinating the contractor, pick-up and delivery of parts.
- Fill in for Operators as needed.
- Responsible for delivering parts or pipe to all fields as needed.
- May assist with site maintenance, including painting and weed-eating.